Document Title: Description file for ECRN-100 High-		Part # 18292	
Resolution Rain Gauge Installation Instructions		Release Date: 9.26.2019	
Rev	Description	Revision By	Date
00	Created file	LAJ	2.15.2019
01	Update the Europe support email address	LAJ	9.26.2019
02	Added trademark symbol to logo	CSC	3.13.2020
03	Added more description to Preparation section	RRK	10.1.2021

Production File Path: <u>http://publications.metergroup.com/Quick%20Start%20Guides/18292_ECRN-</u> 100_Print.pdf

Working File Path:

/Volumes/GoogleDrive/Shared drives/Product Number Library/18200-18299/18292

Dimensions: print size 8.5" wide x 11" tall, cut in half, final size is 8.5" wide x 5.5" tall

Colors: CMYK/Full color 4/4

Printer: In-house printing

Material: Card stock, Bright White, 216 g/m² (folding cardstock)

Finishing: NA

Image below is for reference only. Not to scale.



ECRN-100 HIGH-RESOLUTION RAIN GAUGE INSTALLATION INSTRUCTIONS

18292-03 10.1.2021

METER

Preparation

Inspect and verify that ECRN-100 components are intact. Installation will require a 31.8- to 50.8-mm (1.25- to 2.00-in) diameter mounting pole. Before beginning installation, consider the surroundings and avoid obstructions. Most accurate rain gauge measurements are obtained through installations close to the ground or plant canopy and with a wind shield around the rain gauge to minimize rainfall under-catch from wind blowing across the rain gauge intake. However, this is not always practical, especially if objects above the rain gauge could shield it from receiving representative rainfall.

Set up and test the system (sensors and data loggers) in a lab or office. Ensure the data loggers are using up-todate firmware and software. Check the following locations for firmware and software updates:

ZL6 metergroup.com/zl6-support



Resolution	Volume Per Tip	Rainfall Per Tip
1 tip	4.02 ml/tip	0.2 mm

All products have a 30-day satisfaction guarantee.

Installation

Use the ECRN-100 bracket to mount the rain gauge to the mounting pole at the desired height. Use a wrench to tighten the bolts, securing the rain gauge to the pole. Ensure that it is level (using the bubble level). Plug the sensor cable into the data logger. Use data logger software to apply appropriate settings to the sensors plugged into each data logger port. Gather and secure the cables to the mounting pole in one or more places to relieve strain on the connections.

METER Group, Inc. USA 2365 NE Hopkins Court, Pullman, WA 99163 NORTH AMERICA E support.environment@metergroup.com EUROPE E support.europe@metergroup.com

00