

Document Title: 10HS, Pages		Part # 13508	
		Release Date: 4.15.08	
Rev.	Description	Revision By	Date
2	Updated mineral soil calibration equation.	SLW	8.11.2009
3	Added CE certification page, reformatted.	SLW	11.3.2010
4	METER-ized Edited to match EC-5 manual updates	AG CSC	3.20.2018
5	Corrected calibration equations	CSC	5.10.2018
6	Edited according to DCO 02368	CSC	4.30.2019

Working file path:

<https://drive.google.com/drive/u/1/folders/1JcTIAjfbRvs6xx1FRnXEULDD9y9zwYTg>

Dimensions: 12.5" wide x 8" tall (folded, 8"Hx6.25"W)

Colors: CMYK/Full color 4/4

Printer: Web only

13508-08
4.30.2019

TABLE OF CONTENTS

1. Introduction	1
2. Operation	2
2.1 Installation	2
2.2 Removing the Sensor.....	3
2.3 Connecting.....	3
2.3.1 Connect to METER Data Logger.....	4
2.3.2 Connect to Non-METER Data Logger.....	4
2.4 Interfacing with Data Loggers	6
2.4.1 Data Logger Requirements.....	6
2.4.2 METER Data Loggers.....	6
2.4.3 Non-METER Data Loggers.....	6
3. System	7
3.1 Specifications.....	7
3.2 About 10HS.....	9
4. Service	10
4.1 Calibration	10
4.1.1 Dielectric Calibration.....	10
4.1.2 Mineral Soil Calibration	10
4.1.3 Potting Soil	11
4.2 Troubleshooting.....	12
4.3 Customer Support.....	13
4.4 Terms and Conditions	13
References	14
Index	15